



Lake Lemon SRP Map Showing Sediment Removal Area 110

SRP Completed in 2007

- Legend**
- |                   |                               |
|-------------------|-------------------------------|
| <b>Depth (ft)</b> | <b>Sediment Removal Areas</b> |
| 0 - 1             |                               |
| 1 - 2             |                               |
| 2 - 3             |                               |
| 3 - 4             | <b>District boundary</b>      |
| 4 - 5             |                               |
| 6 - 8             |                               |

The Sediment Removal Area 110 has been completed to provide dock access to lake residents. The barge hauled away 28 loads, totaling 2,240 cubic yards of sediment. An additional 12 loads, totaling 960 cubic yards of sediment was removed by private jobs. A Grand total of 3,200 cubic yards of sediment was removed.

