



Lake Lemon SRP Map Showing Sediment Removal Area 116

SRP Completed in 2006

- Legend**
- | | |
|-------------------|---|
| Depth (ft) | Sediment Removal Areas |
| 0 - 1 |  |
| 1 - 2 | |
| 2 - 3 | |
| 3 - 4 | District boundary |
| 4 - 5 |  |
| 6 - 8 | |

The Sediment Removal Area 116 has been dredged to provide a mooring area for the barge and an unloading area for the dredged material. The barge hauled away 6 loads, totalling 360 cubic yards of sediment.

