





Lake Lemon SRP Map Showing Sediment Removal Area 117

SRP Completed in 2007

- Legend**
- |                   |   |
|-------------------|---|
| <b>Depth (ft)</b> | <b>Sediment Removal Areas</b>   |
| 0 - 1             |  |
| 1 - 2             |   |
| 2 - 3             |   |
| 3 - 4             |   |
| 4 - 5             | <b>District boundary</b>  |
| 6 - 8             |  |

The Sediment Removal Area 117 has been dredged to provide an alternate mooring area for the barge. The barge hauled away 3 loads, totalling 240 cubic yards of sediment.

